MINUTES OF THE 108th MEETING OF SEAC, KERALA, HELD ON 13th& 14th JANUARY, 2020 AT THE CONFERENCE HALL, STATE ENVIRONMENT IMPACT ASSESSMENT AUTHORITY, THIRUVANANTHAPURAM

PARIVESH FILES

AGENDA-3

1. Proposal No. SIA/KL/MIN/125065/2019

<u>**Decision:**</u> The Committee directed the proponent to submit the following documents/details:

- 1. Revised Form 1 M
- 2. Survey map not clear. Not able to check the distance to the nearest house.
- 3. Garand canal is marked through 7.5 m green belt. Rework it (plate 9)
- 4. Details of CER

2. Proposal No. SIA/KL/MIN/125587/2019

<u>**Decision:**</u> The Committee directed the proponent to submit the following documents/details:

- 1. New cluster certificate
- 2. Trees to be removed 40, Green belt with 80 plants. 10% of the land outside project area for afforestation- details needed
- 3. Survey map- Nearest house not marked
- 4. Garland canal through green belt. Rework it
- 5. Details of CER

Mir Mohammed Ali I.A.S

Dr.C.Bhaskaran

3. Proposal No. SIA/KL/MIN/125685/2019

<u>Decision:</u> The Committee directed the proponent to submit the following documents/details:

- 1. Rework project cost
- 2. Revise CER plan

4. Proposal No. SIA/KL/MIN/125990/2019

<u>Decision:</u> The Committee directed the proponent to submit the following documents/details:

- 1. Rework project cost
- 2. An area equivalent to about 10% of the project area is proposed for compensatory mass plantation, outside project area. Affidavit and land details are required.
- 3. CER- Monitorable specifics needed. Letter from GramaPanchayat required.
- 4. Dust mitigation-Drill machines will be equipped with dust collectors... More clarity needed.

5. Proposal No. SIA/KL/MIN/127053/2019

<u>Decision:</u> The Committee directed the proponent to submit the following documents/details:

Mir Mohammed Ali I.A.S

Dr.C.Bhaskaran

- 1. Rework project cost
- 2. Quantity of water reuse is shown as 2KLD. Treatment method is soak pit. Need clarification
- 3. Garland canal is given within green belt. Rework it.
- 4. Contour values absent
- 5. Trees to be cut 28 types: 302 rubber, 248 other trees. Trees to be planted 23 varieties: 200 plants (Mismatch with what is given in form II, it is only 50)
- 6. CER- Rs.50000 is earmarked for drinking water supply. This is difficult to monitor. A sustainable system is required. Exact location and address are needed for other CER components. GramaPanchayat approval needed.

6. Proposal No. SIA/KL/MIN/127237/2019

<u>Decision:</u> The Committee directed the proponent to submit the following documents/details:

- 1. Rework project cost
- 2. Garland canal is given within green belt. Rework it
- 3. Exact location and address are needed for CER components. GramaPanchayat approval needed.
- 4. Trees to be removed 253. Proposal is for planting only 300 trees. (Rs. One lakh budgeted)-Clarify.

7. Proposal No. SIA/KL/MIN/128906/2019

<u>Decision:</u> The Committee directed the proponent to submit the following documents/details:

Mir Mohammed Ali I.A.S

Dr.C.Bhaskaran

- 1. Rework project cost
- 2. OB dump- Location not clear
- 3. Garland canal
- 4. No survey map attached
- 5. CER- GramaPanchayat letter needed

8. Proposal No. SIA/KL/MIN/34642/2019

<u>Decision:</u> The Committee directed the proponent to submit the following documents/details:

1. Rate of production:12890m3/years as per mining plan. This does not match with the following calculations

Block I-139 m*15.8*1.2=2635.44, BlockII-233m*14.1*1.2=3942.36, Total=6577.8 m3

6000m2*1.2=7200m3 (Are=0.60 ha)

- 2. Cost for charity is shown as Rs. 50,000. No specific details- Clarify
- 9. Proposal No. SIA/KL/MIN/41465/2019

<u>Decision:</u> The Committee directed the proponent to submit the following documents/details:

Mir Mohammed Ali I.A.S

Dr.C.Bhaskaran

- 1. Garland canal through green belt. Needs to be revised
- 2. OB site not marked
- 3. Distance to nearest house not marked in survey map, survey map not legible
- **4.** CER- Smart class room, treatment support, solar light, well recharge- Specific details with contact information and GP letter needed. Avoid treatment support component as it is difficult to monitor.

10. Proposal No. SIA/KL/MIN/43206/2019

<u>Decision:</u> The Committee directed the proponent to submit the following documents/details:

- 1. Non cluster certificate available, however there are 10 non-working quarries as per the map given EIA required-Clarify
- 2. OB location not available.
- 3. Survey map
- 4. CER plan

11. Proposal No. SIA/KL/MIN/44488/2019

<u>Decision:</u> The Committee directed the proponent to submit the following documents/details:

Mir Mohammed Ali I.A.S

Dr.C.Bhaskaran

- 1. Rework project cost
- 2. The site is located in Hazard zone orange- Seismic zone 2- Clarify feasibility
- 3. Global Environment Mining Services Validity expired on 15th November 2019
- 4. Two abandoned quarries are present within 500m. One quarry is M/s Wimrock Granites 7.8541 ha (Lease/permit expired on 29/11/2016). Details of other quarry not available with Geology department Clarify
- 5. Garland canal is given through plantation boundary
- 6. Distance to the forest to be checked

12. Proposal No. SIA/KL/MIN/45120/2019

<u>Decision:</u> The Committee directed the proponent to submit the following documents/details:

- 1. Revise project cost
- 2. Cluster certificate
- 3. Survey map with distance to nearest house
- 4. Drainage map
- 5. OB location
- 6. Biodiversity assessment
- 7. CER plan

13. Proposal No. SIA/KL/MIN/45585/2019

<u>Decision:</u> The Committee directed the proponent to submit the following documents/details:

Mir Mohammed Ali I.A.S

Dr.C.Bhaskaran

- 1. A quarry is visible in Google map-Clarify cluster condition
- 2. Furnish maps including production map, survey map, OB location site etc
- 3. CER to be reworked, letter from GP required, specific details of each project needed

14. Proposal No. SIA/KL/MIN/46090/2019

<u>**Decision:**</u> The Committee directed the proponent to submit the following documents/details:

- 1. Non cluster certificate, dated:28/10/2019 is not legible. Unable to verify
- 2. Garland canal is given in green belt. Need to be revised
- 3. CER- Pazhukkakkulamthodu protection with granite stones- Explore protection with coir geo textile.

15. Proposal No. SIA/KL/MIN/46108/2019

<u>Decision:</u> The Committee directed the proponent to submit the following documents/details:

- 1. Consultant recognition expired on 15th Nov 2019
- 2. CER plan
- 3. Garland drainage map
- 4. Clarify the distance to nearest house survey map not clear

16. Proposal No. SIA/KL/MIN/46290/2019

<u>**Decision:**</u> The Committee directed the proponent to submit the following documents/details:

- 1. Mining plan available. Garlanddrains, silt traps need clarity.
- 2. Rework project cost.

Mir Mohammed Ali I.A.S

Dr.C.Bhaskaran

17. Proposal No. SIA/KL/MIN/76720/2018

<u>Decision:</u> The Committee directed the proponent to submit the following documents/details:

1. Application for EC with all required documents.

18. Proposal No. SIA/KL/MIN/93730/2019

<u>**Decision**</u>: As no document is seen attached to the proposal,the Committee directed the proponent to submit all the required documents

Mir Mohammed Ali I.A.S

Dr.C.Bhaskaran